



EWN:5193010935000

No picture available	encoder ROD 431.035 (1024 impulses)	
	Notes	
	Successor hint: Repair part This product is a spare part product. More information you'll get via "Alternative Buying Options". If you need assistance please contact our local Siemens office	
	List Price	Show prices
	Customer Price	Show prices
	Alternative Buying Options	For this product we offer a fast delivery and if possible an exchange or repair part. For further information please contact your local Spares&Repair Partner
DataSheet in PDF		Download
Manuals, Certificates, FAQs...		Service & Support

Product

Article Number	EWN:5193010935000
Product Description	encoder ROD 431.035 (1024 impulses)
Product family	Not available
Product Lifecycle (PLM)	PM300:Active Product
Notes	Successor hint: Repair part This product is a spare part product. More information you'll get via "Alternative Buying Options". If you need assistance please contact our local Siemens office

Price data

Price Group	761
List Price	Show prices
Customer Price	Show prices
Surcharge for Raw Material	see also metal factor (further details are available on the help page)
Metal Factor	see also metal factor (further details are available on the help page)

Delivery information

Export Control Regulations	ECCN : N / AL : N
Standard lead time ex-works	2 Day(s)
Net Weight (kg)	0,200 Kg
Package size unit of measure	Not available
Quantity Unit	1 Piece
Packaging Quantity	1

Additional Product Information

EAN	Not available
UPC	804766674525
Commodity Code	90314990
LKZ_FDB/ CatalogID	RP-MOTO
Product Group	9695
Group Code	R220
Country of origin	Germany
Compliance with the substance restrictions according to RoHS directive	Since: 21.07.2019
Product class	A: Standard product which is a stock item could be returned within the returns guidelines/period.
WEEE (2012/19/EU) Take-Back Obligation	No
REACH Art. 33 Duty to inform according to the current list of candidates	

Classifications

Not available
