## 6SE6400-1PB00-0AA0



\*\*\*spare part\*\*\* MICROMASTER 4 PROFIBUS module For mechanical reasons, for MM4 FX/GX the plug 6GK1500-0EA02 must be used

## Notes

This product is a Spare Part, please visit the Spares & Service section for more information If you need assistance please contact our local Siemens office

List Price	Show prices
Customer Price	Show prices
Service & Support (Manuals, Certificates, FAQs)	Download

Image similar

## Product

6SE6400-1PB00-0AA0
***spare part*** MICROMASTER 4 PROFIBUS module For mechanical reasons, for MM4 FX/GX the plug 6GK1500-0EA02 must be used
Not available
PM410:Product cancellation
Product is cancelled since: 01.10.2019
This product is a Spare Part, please visit the Spares & Service section for more information If you need assistance please contact our local Siemens office
S60 / 3A1
Show prices
Show prices
None
None
ECCN: N/AL: N
1 Day/Days
0,300 Kg
105,00 x 215,00 x 60,00
MM
1 Piece
1
4019169447287
Not available
85049090
DA51-A
9848
R2S3
Great Britain
Since: 29.06.2006
A: Standard product which is a stock item could be returned within the returns guidelines/period.

## REACH Art. 33 Duty to inform according to the current list of candidates Classifications

WEEE (2012/19/EU) Take-Back Obligation

Not available

Yes